



Adopt-A-Stream: Highlights from the 2008 Stream habitat assessment

Based off of observations made in the Measuring and Mapping Program
 For all available data, contact Paul Steen at HRWC, psteen@hrwc.org

Site Number	Stream Name	Road Crossing	Date	Avg Depth (ft)	Max Depth (ft)	% Fine Substrate	% Coarse Substrate	Rifle Embeddedness	Bank Height (ft)	% Banks Bare	Bad Appearance or Odor?	Proc. 51 Score (100 max)
2008 Sites												
4	Boyden Creek	Huron River Drive	7/29/2008	0.7	1.5	26	72	25-50%	2.3	25	No	47.5
7	Davis Creek	Pontiac Trail	8/24/2008	0.7	1.4	34	66	50-75%	2.2	0	No	73.5
13	Fleming Creek	Warren Road	8/6/2008	0.8	2.8	47	53	< 25%	0.6	7.5	No	82.5
47	Huron River	Commerce Road	7/31/2008	0.7	1.6	18	82	25-50%	3.1	50	No	51
26	Huron River	Zeeb Road	8/11/2008	1.4	3.7	34	66	< 25%	1.1	30	No	76
27	Malletts Creek	Chalmers	7/30/2008	0.8	3.2	7	93	25-50%	2.6	50	No	61
34	Mill Creek	Letts Cr at M-52	9/4/2008	0.5	1.0	5	95	< 25%	4.3	0	No	70.5
77	Millers Creek	Hubbard	8/21/2008	0.3	1.8	1	99	25-50%	2.6	25	No	51.5
76	Millers Creek	Huron Pkwy	8/10/2008	0.2	1.4	94	6	>75%	1.1	5	No	31
73	Millers Creek (E Branch)	Baxter Road	8/24/2008	0.1	2.4	75	25	25-50%	3.1	90	No	27.5
75	Millers Creek (Trib)	Green Road	8/1/2008	0.1	0.2	90	7	< 25%	4.4	47	No	40
74	Millers Creek (Trib)	Lakehaven Ct	8/2/2008	0.6	6.0	70	30	< 25%	1.3	0	No	49
67	Pettibone Creek	Commerce Road	8/24/2008	0.6	1.4	48	45	50-75%	1.4	12.5	No	56.5
50	South Ore Creek	Lake Ridge	8/27/2008	0.4	2.5	9	90	< 25%	1.2	25	No	63.75
88	Woods Creek	Renton Road	8/24/2008	0.3	0.9	89	0	>75%	2.2	10	No	51
87	Woods Creek	Martinsville Road	8/17/2008	0.4	1.0	94	0	>75%	1.9	0	No	49
Older Sites												
1	Arms Creek	Walsh Road	8/29/2004	0.8	1.4	62	37	< 25%	1.9	40	Yes	69
3	Boyden Creek	Golf Course	7/30/2007	0.5	1.8	28	61	< 25%	1.3	10	No	73.5
2	Boyden Creek	Delhi	8/4/2007	0.3	1.1	45	54	50-75%	1.5	0	No	78.5
45	Chilson Creek	Brighton Road	8/6/2005	0.5	0.9	57	43	25-50%	0.6	0	No	67.5
5	Chilson Creek	Chilson Road	8/14/2007	0.3	0.9	47	52	< 25%	1.4	0	No	87
81	Davis Creek	11 Mile Road	7/28/2005	0.5	1.0	81	19	< 25%	1.5	0	No	60
6	Davis Creek	Doane Road	7/28/2006	1.2	2.2	68	32	< 25%	3.0	0	No	87.5
84	Fleming Creek	Galpin	8/4/2004	0.5	0.9	29	67	< 25%	1.5	8	No	80.5

Site Number	Stream Name	Road Crossing	Date	Avg Depth (ft)	Max Depth (ft)	% Fine Substrate	% Coarse Substrate	Rifle Embeddedness	Bank Height (ft)	% Banks Bare	Bad Appearance or Odor?	Proc. 51 Score (100 max)
12	Fleming Creek	Radrick Farms	8/9/2006	1.2	4.0	6	94	25-50%	1.3	20	No	68.5
11	Fleming Creek	Geddes Road	9/14/2006	1.5	3.4	19	81	< 25%	1.6	15	No	85.5
9	Fleming Creek	Botanical Gardens	10/22/2005	0.7	1.9	47	53	25-50%	2.2	10	No	80
8	Greenoak Creek	Rushton Road	8/6/2006	0.5	1.3	30	65	25-50%	1.4	5	Yes	82.5
15	Hay Creek		8/6/2005	0.3	0.7	66	21	< 25%	1.4	0	No	75.5
20	Honey Creek	Wagner Road	8/14/2004	0.7	1.9	30	66	< 25%	1.4	10	No	77
19	Honey Creek	Pratt Road	8/2/2005	1.3	2.5	66	22	>75%	1.5	0	No	53
18	Honey Creek	Jackson Road	8/21/2005	0.5	1.0	54	46	25-50%	1.4	10	No	72.5
16	Honey Creek (N)	Darwin Road	8/12/2007	0.5	1.3	42	53	25-50%	3.0	0	No	67.5
21	Horseshoe Creek		8/14/2007	0.4	2.5	19	80	< 25%	1.9	10	Yes	90.5
63	Hummocky Lick	M-36	9/16/2006	0.2	0.5	86	10		1.1	10	No	67.5
22	Huron Creek	Near the mouth	7/30/2005	0.2	0.7	8	92	25-50%	1.1	5	No	87.5
64	Huron River	Proud Lake Rec Area	7/28/2006	1.6	2.8	77	18	25-50%	1.3	20	No	60
62	Huron River	Bell Road	9/15/2007	1.7	4.0	10	90	< 25%	2.1	0	No	88.5
61	Huron River	Island Park	7/29/2006	0.9	2.0	22	69	< 25%	3.7	0	No	71
51	Huron River	US-23 (Liv. Co)	7/29/2007	2.4	3.6	72	25		1.7	40	No	57.5
25	Huron River	White Lake Road	8/20/2006	0.4	0.8	16	84	< 25%	1.4	5	No	90.25
24	Huron River	Cross Street	8/25/2005	2.1	3.9	4	96	50-75%	2.7	5	No	68.5
23	Huron River	Flat Rock	9/17/2005	1.3	2.2	0	100	< 25%	2.2	10	No	81
56	Malletts Creek	Main Street	8/23/2005	0.4	1.1	40	60	50-75%	1.0	30	No	49.5
29	Malletts Creek	Scheffler	8/6/2004	1.0	2.5	54	46	< 25%	2.9	25	No	71
28	Malletts Creek	I-94	8/8/2005	0.5	1.3	29	71	< 25%	1.8	100	Yes	47
30	Mann	VanAmberg Road	9/10/2005	0.5	0.9	32	65	25-50%	1.1	9	No	69.5
80	Mill Creek	Shield Road	9/3/2007	1.7	4.5	85	13		0.5	5	No	45.5
79	Mill Creek	Warrior Park	7/31/2004	1.0	1.9	9	91	< 25%	3.0	0.05	No	71.5
57	Mill Creek	Klinger Road	9/10/2005	1.0	2.6	56	44	25-50%	3.1	10	No	77
55	Mill Creek	Manchester Road	8/21/2005	0.7	1.3	55	37	< 25%	2.1	0	No	67.5
33	Mill Creek	Jackson Road	10/7/2007	0.7	1.5	23	76	< 25%	3.7	0	No	78.5
32	Mill Creek	Ivey Road	9/10/2005	0.2	0.4	39	58	< 25%	1.5	10	No	57
31	Mill Creek	Fletcher Road	8/6/2005	1.2	2.4	21	79	50-75%	3.2	10	No	69.5
35	Millers Creek	Glazier Way	7/31/2007	0.2	0.7	22	70	25-50%	8.6	75	No	44.5
72	Millers Creek (W Branch)	Plymouth Rd	7/29/2006	0.4	1.5	84	13	< 25%	3.6	80	No	49.5
65	Norton Creek	West Maple Road	8/6/2005	0.7	1.6	67	31	< 25%	1.9	20	No	69
68	Pettibone Creek	Livingston Road	11/3/2007	0.6	1.4	19	81	< 25%	0.5	0	No	97
58	Portage Creek	Unadilla	8/2/2005	0.9	2.0	94	6	< 25%	2.4	0	No	67

Site Number	Stream Name	Road Crossing	Date	Avg Depth (ft)	Max Depth (ft)	% Fine Substrate	% Coarse Substrate	Rifle Embeddedness	Bank Height (ft)	% Banks Bare	Bad Appearance or Odor?	Proc. 51 Score (100 max)
37	Portage Creek	Dexter-Townhall Road	9/3/2006	1.1	4.3	29	71	< 25%	2.6	0	No	82
49	S Branch Huron River	Silver Lake	7/25/2007	0.9	2.5	45	54	< 25%	1.6	100	No	83
52	South Ore Creek	Bauer Road	8/28/2005	0.7	1.6	65	34	< 25%	0.4	5	No	72
40	South Ore Creek	Hamburg Road	8/9/2006	1.0	2.2	42	58	50-75%	1.0	10	No	75.5
41	Swift Run	Swift Run	7/29/2006	0.6	1.3	51	49	25-50%	2.3	35	No	61
43	Traver Creek	Dhu Varren Road	8/11/2004	0.3	0.8	29	68	< 25%	0.7	0	No	90
42	Traver Creek	Broadway	8/12/2006	0.2	0.6	25	75	< 25%	2.3	5	No	61.5
82	Walker Creek	8 Mile Road	10/28/2007	0.4	1.1	57	37	50-75%	1.8	35	No	74
46	Woodruff Creek	Buno Road	7/20/2002	0.4	0.9	93	4	< 25%	1.7	3	No	67.40740741
44	Woodruff Creek	Maxfield Road	7/29/2006	0.4	0.8	85	10	>75%	1.3	1	No	62
14	Woods Creek	L Huron Metropark	8/27/2007	0.7	1.7	26	72	< 25%	3.5	30	No	72.5